General Environmental Incident Summary

Incident: 3855 Date/Time Notice: 8/6/2015 1210 DEM Incident No:

Responsible Party: 5th Bomb Wing

Date Incident:8/4/2015Time Incident:1100Duration:2 daysCounty:WardTwp:157Rng:83Sec:13Qtr:SW SE SW

Lat: 48.41530 Long: -101.33360 Method: Navigation quality GPS

Location Description: Corner of Peacekeeper Place and Bomber Boulevard on Minot AFB, 13 miles

north of Minot, ND.

Submitted By: Michael Getty Affiliation:

Address: 5 DES/CEIE

445 Peacekeeper Place

City: Minot AFB State: ND Zip: 58705

Received By:

Contact Person: Michael Getty

201 Summit Drive Minot FB, ND 58705

Distance Nearest Occupied Building: 500 Feet Release Contained: Yes

Type of Incident: Pipeline Leak

Description of Released Contaminant: MOGAS

Volume Spilled: 1280.00 gallons Ag Related: No

EPA Extremely Hazardous Substance: No Reported to NRC: Unknown

Cause of Incident:

A primary transfer pipe associated with the ASTs at the military service station malfunctioned (broke) and leaked 1280 gallons of MOGAS into the secondary containment piping which then leaked into the underground containment pit where it was totally contained

Risk Evaluation:

None.

of Fatalities: 0 # of Injuries: 0 Affected Medium: 01 - air

Potential Environmental Impacts:

None. Release was 100% contained - it did not reach water or soil.

Action Taken or Planned:

The fuel was removed from the containment pit and the residue was mopped up with absorbent pads. The removed fuel was recycled. The broken pipe was repaired.

Wastes Disposal Location: 1200 gallons were recycled. The absorbent material was containerized

and taken to the Minot AFB HAZMART for compliant disposal.

Agencies Involved:

Updates

Date: 8/6/2015 Status: Reviewed - No Action Required Author: Crowdus, Kory

Updated Volume:

Notes:

Release was contained in underground containment pit. No follow-up required.